File Original and First Copy with Department of Ecology Second Copy — Owner's Copy Third Copy — Driller's Copy

WATER WELL REPORT

| pplication | Nο | | |
|------------|----|--|--|
| | | | |

| OWNER: Name RAY GABELLEN | | | | |
|--|---|---|-------------|----------------|
| · / · · · · · · · · · · · · · · · · · · | Address 5785 | S. BAYVIEW I | RI. LA | ander/ |
|) LOCATION OF WELL: County Island | | WW JW & Sec 5 To | | w.м. |
| aring and distance from section or subdivision corner 1200' S. | and 500' A | 5. of NW. Corner | Sec. | <u>5, </u> |
|) PROPOSED USE: Domestic [] Industrial [] Municipal | (10) WELL LOC | } : | | |
| Irrigation □ Test Well □ Other □ | | y color, character, size of mater ifers and the kind and nature o | | |
| TVDF OF WORK. Owner's number of well | stratum penetrated, w | ith at least one entry for each | thange of | or matton. |
| Owner's number of well (if more than one) New well Method: Dug Dored D | | MATERIAL | FROM | TO |
| Deepened | | P 50/L | 1 | 20 |
| Reconditioned Rotary Jetted | SAUN IL | AND PAN with racks | 20 | NO |
| Drilled ft. Depth of completed well the ft. | SAND + | Vin Water | 153 | 153 |
| CONSTRUCTION DETAILS: | | <u></u> | | |
| Casing installed: 6 Diam from 6 ft. to 187 ft. | | | + | |
| Threaded D Diam, from ft. to ft. | | | | |
| Welded Diam. from ft. to ft. | | | | <u> </u> |
| Perforations: Yes 🔲 No 📕 | | | + | - |
| Type of perforator used | | | + | - |
| SIZE of perforations in. by in. perforations from ft. to ft. | | | - | |
| perforations from ft. to ft. | | | | |
| perforations from ft. to ft. | | | | |
| Screens: Yes No 🗆 | | | | |
| Manufacturer's Name DOK Type STANKESS STANK Model No. With Manufacturer's Name Model N | | | _ | - |
| Diam Slot size from St. tt. to | | | | |
| Diam Slot size from ft. to ft. | | | | |
| Gravel packed: Yes No M Size of gravel: | | | | |
| Gravel placed from | | | | _ |
| • • • | Į. | | | - |
| Surface seal: Yes No D To what depth? ft Material used in seal BENTONITE | | | | |
| Did any strata contain unusable water? Yes \(\) No | | | | |
| Type of water? Depth of strata Method of sealing strata off | · | | | |
| | | | | <u> </u> |
| 7) PUMP: Manufacturer's Name Goulde Type: Submersible HP | | | | |
| | - | | | |
| above mean sea level above mean sea level | | | | |
| tatic level | " | | | |
| Artesian water is controlled by(Cap, valve, etc.) | | | | |
| and a second de | · | 1 | 2/10 | 9/ |
| 9) WELL IESIS. lowered below static level | Work started | 19. Completed | 2/10 | 19.0 |
| Was a pump test made? Yes No I If yes, by whom? Of the Array of the drawdown after hree hree hree hree hree hree hree h | well drilli | ER'S STATEMENT: | | |
| neto. To gurnamento per properties de la companya d | _ This well was | drilled under my jurisdicti | on and thi | s report i |
| 0 0 | = | of my knowledge and belie | , _ | |
| Recovery data (time taken as zero when pump turned off) (water leve measured from well top to water level) | NAME B+L | U WEH DRILLIN | a Co |) . |
| Time Water Level Time Water Level Time Water Level | (F | Person, firm, or corporation) | (Type or | |
| | Address P.O. | BOX 55 FI | REELAN | 10, W |
| | , | | | |
| | | 1 / | | |
| Date of test | [Signed]ئالىتىدىدى | 10, 1620 | | |
| Date of test | 4 . | (Well Driller) | | 0 |